

1023 Transverse crack in the heat affected zone

